



**JABATAN LAUT WILAYAH TENGAH  
( SELANGOR, NEGERI SEMBILAN & MELAKA )  
PETI SURAT 268, JALAN FORESHORE  
42000 PELABUHAN KLANG  
SELANGOR, MALAYSIA**

Telefon: 03-3169 5100  
Faks: 03-3165 3540

Emel : pjlwt@marine.gov.my  
Laman Web : <http://www.marine.gov.my>  
Kawat : MARINE PELABUHAN KLANG



**MS ISO 9001**  
Cert. No : KLR 0403591 B  
Cert. No : KLR 0403591 N  
Cert. No : KLR 0403591 M

**PEKELILING PELABUHAN NO. 01/2009**  
**PORT CIRCULAR NO. 01/2009**

DARIPADA : PENGARAH LAUT WILAYAH TENGAH  
FROM : DIRECTOR OF MARINE CENTRAL REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN  
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA  
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS &  
AGENTS AND THE GENERAL SHIPPING COMMUNITY

TARIKH / DATED : 5hb MEI 2009 / 5<sup>th</sup> MAY 2009

**KERJA-KERJA Pengerukan Kecemasan  
di Labuhan untuk Pelabuhan Utara  
dan Pelabuhan Barat, Pelabuhan  
Kelang, Malaysia**

Adalah dimaklumkan bahawa kerja-kerja pengerukan di dermaga Pelabuhan Utara dan Pelabuhan Barat akan dijalankan oleh Syarikat Integrated Marine Works dan butiran kerja-kerja pengerukan adalah seperti berikut ;

Tarikh : 6hb Mei 2009 hingga 6hb Mac 2010

**Kawasan Pengerukan :**

a) Pelabuhan Utara (Dermaga 17 - 20)

	Latitude	Longitude
A	03° 02' 00.65" N	101° 21' 25.80" E
B	03° 02' 00.56" N	101° 21' 24.18" E
C	03° 01' 57.05" N	101° 21' 22.65" E
D	03° 02' 28.26" N	101° 21' 22.65" E

b) Pelabuhan Barat (Dermaga B1-B-B16)

	Latitude	Longitude
A	02° 57' 31" N	101° 18' 30" E
B	02° 57' 36" N	101° 18' 27" E
C	02° 56' 40" N	101° 18' 00" E
D	02° 56' 42" N	101° 17' 58" E
E	03° 18' 19" N	100° 54' 34" E
F	02° 55' 34" N	101° 17' 19" E

**EMERGENCY DREDGING WORKS AT WHARF  
FOR NORTH PORT AND WEST PORT,  
KELANG PORT, MALAYSIA**

*This is to notify that the dredging works at North Port and West Port wharf will be carried out by Integrated Marine Works and the details of the dredging works are as follows ;*

*Dates : 6<sup>th</sup> May 2009 to 6<sup>th</sup> March 2010*

**Dredging Area :**

a) North Port (Wharf 17 - 20)

	Latitude	Longitude
A	03° 02' 00.65" N	101° 21' 25.80" E
B	03° 02' 00.56" N	101° 21' 24.18" E
C	03° 01' 57.05" N	101° 21' 22.65" E
D	03° 02' 28.26" N	101° 21' 22.65" E

b) West Port (Berth B1-B-B16)

	Latitude	Longitude
A	02° 57' 31" N	101° 18' 30" E
B	02° 57' 36" N	101° 18' 27" E
C	02° 56' 40" N	101° 18' 00" E
D	02° 56' 42" N	101° 17' 58" E
E	03° 18' 19" N	100° 54' 34" E
F	02° 55' 34" N	101° 17' 19" E

**Kawasan Pelupusan :**

	Latitude	Longitude
A	02° 56' 33" N	101° 07' 16" E
B	02° 54' 00" N	101° 10' 05" E
C	02° 54' 57" N	101° 05' 50" E
D	02° 54' 29" N	101° 07' 58" E

**Vesel yang terlibat :**

Nama Vesel	Jenis Vesel
Inai Melawis	Grab Dredger
Inai Teratai 113	Bot Tunda
Inai Teratai 33	Bot Tunda
Inai Teratai 88	Bot Tunda
Inai Lily 11	Bot Sauh
Inai Rose 1202	Split Hopper
Inai Rose 33	Split Hopper

Carta terlibat ;

MAL 5307, 5300

Semua vesel-vesel dan pelaut-pelaut adalah dinasihatkan untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan berkerja.

Sekian, terima kasih.

**"BERKHIDMAT UNTUK NEGARA"**

Saya yang menurut perintah,

**(HAZMAN BIN HUSSEIN)**

Pengarah Laut / Director of Marine  
Wilayah Tengah / Central Region

**Dumping Ground :**

	Latitude	Longitude
A	02° 56' 33" N	101° 07' 16" E
B	02° 54' 00" N	101° 10' 05" E
C	02° 54' 57" N	101° 05' 50" E
D	02° 54' 29" N	101° 07' 58" E

**Vessel Involved :**

Name of Vessel	Type of Vessel
<i>Inai Melawis</i>	<i>Grab Dredger</i>
<i>Inai Teratai 113</i>	<i>Tug Boat</i>
<i>Inai Teratai 33</i>	<i>Tug Boat</i>
<i>Inai Teratai 88</i>	<i>Tug Boat</i>
<i>Inai Lily 11</i>	<i>Anchor Boat</i>
<i>Inai Rose 1202</i>	<i>Split Hopper</i>
<i>Inai Rose 33</i>	<i>Split Hopper</i>

*Chart effected ;*

*MAL 5307, 5300*

*All vessel and mariners in the vicinity are advised to navigate with caution and keep clear of the working area.*

*Thank you.*

