



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**\*85/2022 - TG PO BUOYS REPOSITIONED**

Mariners are advised that the following buoys have been repositioned as follows:

| Buoys       | Characteristic   | Move from                         |                                   |
|-------------|------------------|-----------------------------------|-----------------------------------|
|             |                  | existing position                 | to new position                   |
| Buoy No. 5  | <i>Fl. G. 5s</i> | 01°42'19.440"N<br>110°33'07.412"E | 01°42'19.900"N<br>110°33'02.500"E |
| Buoy No. 6  | <i>Fl. R. 5s</i> | 01°42'19.013"N<br>110°33'17.356"E | 01°42'18.700"N<br>110°33'22.100"E |
| Buoy No. 7  | <i>Fl. G. 5s</i> | 01°41'05.051"N<br>110°32'24.814"E | 01°41'08.400"N<br>110°32'21.000"E |
| Buoy No. 8  | <i>Fl. R. 5s</i> | 01°40'59.456"N<br>110°32'32.570"E | 01°40'57.300"N<br>110°32'36.000"E |
| Buoy No. 9  | <i>Fl. G. 5s</i> | (New)                             | 01°39'24.500"N<br>110°31'23.300"E |
| Buoy No. 10 | <i>Fl. R. 5s</i> | (New)                             | 01°39'15.800"N<br>110°31'40.600"E |
| Buoy No. 11 | <i>Fl. G. 5s</i> | (New)                             | 01°38'59.300"N<br>110°30'27.900"E |
| Buoy no. 12 | <i>Fl. R. 5s</i> | (New)                             | 01°38'43.400"N<br>110°30'38.200"E |

*Positions in WGS 84 Datum*

2. Mariners are advised to update their affected charts accordingly.

Charts : SAR 11, SAR 12, SAR 13 & SAR 101

Source : Sarawak Region Marine Department

Date : 14<sup>th</sup> July 2022

**" BERKHIDMAT UNTUK NEGARA "**

**[ RADUAN BIN SERAP ]**

For Director of Marine Sarawak

**"Safer Ships, Secure Ports, Cleaner Seas"**



Cert. No: ISO 9001-0047621, ISO 9001-0047600