



PENINSULAR NOTICE TO MARINERS NTM - 91(T)/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
 Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters, East Johor.

Charts Affected : MAL 625, MAL 68
 BA 2470

SUBMARINE CABLE REPAIR WORKS (EAC2)
JOHOR WATERS

Mariners are advised that East Asia Crossing Phase 2 (EAC2) submarine cable repair is being carried out in Johor Waters.

Duration: **15th May 2023 until 24th July 2023**

Vessel Involved:

Name	: RV GARDA	Name	: KDDI CABLE INFINITY
Type	: Research Vessel	Type	: Cable Layer
Flag	: Indonesia	Flag	: Japan
Call Sign	: YCRY2	Call Sign	: 7KDM

Area: The work area is enclosed by an imaginary lines connecting the following points:

Point	Latitude	Longitude
1	01° 27.0752' N	104° 33.8974' E
2	01° 27.1398' N	104° 33.9773' E
3	01° 28.3639' N	104° 35.4866' E
4	01° 28.6263' N	104° 35.8754' E
5	01° 29.6744' N	104° 37.4286' E
6	01° 29.9188' N	104° 37.6555' E
7	01° 30.3497' N	104° 38.0555' E
8	01° 31.0384' N	104° 38.6944' E
9	01° 32.4956' N	104° 39.9581' E
10	01° 32.7460' N	104° 40.2251' E
11	01° 32.8374' N	104° 40.4850' E
12	01° 32.8051' N	104° 40.8027' E
13	01° 32.7494' N	104° 41.3514' E

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
 CERT. NO.: QMS 03602

Point	Latitude	Longitude
14	01° 32.8413' N	104° 41.5671' E
15	01° 33.0613' N	104° 41.7897' E
16	01° 33.2850' N	104° 42.0160' E
17	01° 33.4237' N	104° 42.1329' E
18	01° 34.1803' N	104° 42.7706' E
19	01° 34.6665' N	104° 43.0734' E
20	01° 35.7958' N	104° 44.1700' E
21	01° 36.5041' N	104° 44.7579' E
22	01° 37.5350' N	104° 45.3018' E
23	01° 38.2081' N	104° 45.6500' E
24	01° 38.3667' N	104° 45.7320' E
25	01° 39.8259' N	104° 46.2843' E
26	01° 40.0292' N	104° 46.3613' E
27	01° 41.2395' N	104° 46.9670' E
28	01° 41.8453' N	104° 47.2702' E
29	01° 42.6390' N	104° 47.6137' E
30	01° 43.9489' N	104° 48.3503' E
31	01° 46.6231' N	104° 49.6468' E
32	01° 46.6393' N	104° 49.6549' E
33	01° 47.7131' N	104° 50.1893' E
34	01° 48.8144' N	104° 50.7374' E
35	01° 50.2741' N	104° 51.4536' E
36	01° 51.4261' N	104° 52.0828' E
37	01° 52.2424' N	104° 52.4193' E
38	01° 52.5424' N	104° 52.5675' E
39	01° 53.5907' N	104° 53.1767' E
40	01° 54.6886' N	104° 53.6498' E
41	01° 55.2154' N	104° 53.8737' E
42	01° 56.3187' N	104° 54.3426' E
43	01° 57.3586' N	104° 54.8484' E
44	01° 57.7158' N	104° 55.1493' E
45	01° 58.0535' N	104° 55.3070' E
46	01° 58.4229' N	104° 55.5603' E
47	01° 59.2826' N	104° 55.9986' E
48	01° 59.8931' N	104° 56.3098' E
49	02° 00.5065' N	104° 56.5312' E
50	02° 01.3075' N	104° 56.9203' E
51	02° 02.3415' N	104° 57.4591' E
52	02° 03.4288' N	104° 57.9189' E
53	02° 05.8019' N	104° 59.2185' E
54	02° 06.0185' N	104° 59.3371' E
55	02° 09.7293' N	105° 01.0552' E
56	02° 10.7588' N	105° 01.3647' E
57	02° 11.7182' N	105° 01.7683' E
58	02° 12.3090' N	105° 02.0526' E

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602

	02° 12.4766' N	105° 02.1001' E
	02° 12.8373' N	105° 02.2023' E
	02° 13.3297' N	105° 02.4133' E
	02° 13.5490' N	105° 02.4741' E

Above coordinates are referenced to Datum: WGS-84

Mariners are advised to navigate with caution when in the vicinity and keep clear of the working area.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)

for The Director General,
Marine Department Malaysia.

15th April 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602