JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA

NOTICE TO MARINERS

NTM 102(T)/1999

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klan, Malaysia.
Tel: 03 3686616 Fax: 03 368 5289 E-mail: kpgr@marine.gov.my Web site: http://www.marine.gov.my

Authority : Director General of Marine, Peninsular Malaysia

Position : MALACCA STRAITS

Charts Affected : BA 3946 , MAL 532

Publication Affected: NP 44, NP 79

NEW LIGHT BUOY ESTABLISHED - MALACCA STRAITS TRAFFIC SEPARATION SCHEME (TSS)

1. Mariners are advised that an Isolated Danger light buoy has been established for marking the wreck of MV JENWIN. Details of the buoy are as follow :-

Position:	**Latitude**	**02° 16.07 ' N**
(approx)	**Longitude**	**101° 47.69' E**
Light Characteristic:		**FL(2)W 10s**
Range:		**7 N.M.**
Colour:		**Black with a red horizontal band**
Shape:		**Pillar**
Top Mark:		**Double Black Sphere**

2. Mariners are advised to navigate with extreme caution when navigating in the vicinity.

(Capt. Nazri Bin Abu Hassan)
for Director General of Marine
Peninsular Malaysia.

20 December 1999