HYDROGRAPHIC OFFICE
SARAWAK MARINE DEPARTMENT

NOTICE TO MARINERS
(NOTIS PELAUT)

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422
Website : www.jls.gov.my

BORNEO NORTH WEST COAST

40/2010(T) - BINTULU PORT, SOUTH ACCESS CHANNEL, BUOY J - MISSING

Bintulu Port, South Access Channel, **Buoy J**, ***Fl.R.5s***, position **03° 15' 21".454 N, 113° 02' 31".301 E** is missing.

2. Mariners are advised to take extra caution when navigating in the area.

Chart : SAR 4001
Source : Sarawak Marine Department
Date : 04th August 2010

"BERKHIDMAT UNTUK NEGARA"

[SARKAWI BIN NUMAN]
For Director of Marine Sarawak