HYDROGRAPHIC OFFICE
MALAYSIA MARINE DEPARTMENT SARAWAK REGION

NOTICE TO MARINERS
(NOTIS PELAUT)

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my

BORNEO NORTH WEST COAST

*52/2025 – NAVIGATION AIDS PERMANENTLY DISCONTINUED AT KUALA TATAU AND KUALA KEMENA, BINTULU

Delete lights as follows:

Location Name	Characteristic	Latitude	Longitude
KI. Tatau Beacon	Fl. 4s	03°05'03.361"N	112°47'48.202"E
KI. Tatau Rear Lts Beacon	Fl. 4s	03°05'01.262"N	112°47'48.901"E
Wesonic-8 Wk Beacon	Fl. (2). 10s	03°11'00.800"N	113°01'17.200"E

Positions in WGS 84 Datum

2. Mariners are advised to update their affected charts and Sarawak List of Lights (SNP-4) accordingly.

Charts: SAR 1, SAR 2, SAR 4, SAR 6, SAR 73, SAR 402 & SAR 4002
Source: Malaysia Marine Department, Sarawak Region
Date : 6th May 2025

" BERKHIDMAT UNTUK NEGARA "

[SYAHRIZAN BIN JILI]
for Director of Marine Sarawak