MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PO BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN

PENINSULAR NOTICE TO MARINERS NTM 146 / 2026

Telephone: 03-3162 9797 | Email : mmcc@marine.gov.my | Website : http://www.marine.gov.my

Authority : Director of Marine, Malaysia

Position : Johor Waters

Charts Affected : MAL 6130 & MAL 6134
BA 4043

SM 1 SPECIAL MARK LIGHT BUOY RESTORED TO NORMAL JOHOR WATERS

Mariners are advised that SM 1 Special Mark Light Buoy has been restored to normal. The details are as follows:

Name **:** SM 1 Special Mark Light Buoy

Position **:** Lat. 01° 25.814’ N; Long. 104° 00.602’ E

Type **:** Special Mark

Light Characteristic **:** FL.Y.5s

Mariners are advised to navigate with caution when in the vicinity. This notice cancels NTM 140(T)/2026.

(EMIZUL FADLY MASDEK)
for The Director General
Malaysia Marine Department
28th July 2026