MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA

PENINSULAR NOTICE TO MARINERS NTM 160 (T) / 2026

Telefon: 03-3162 9797 | Emel : kpgr@marine.gov.my | Laman Web : http://www.marine.gov.my

Authority : Director of Marine, Malaysia

Position : Kelantan, Tok Bali Waters

Charts Affected : MAL 664
BA 771

TOK BALI 1R (TB1R) LIGHT BUOY OFF STATION KELANTAN WATERS

Mariners are advised that an Isolated danger mark light buoy is off station. The details are as follows:

Name : **TOK BALI 1R (TB1R)**

Position : **Lat. 05° 54.640' N,**
Long. 102° 29.489' E

Light Characteristic : **Fl (2).R.6s**

Type of Mark : **Porthand**

Mariners are advised to navigate with caution when in the vicinity.

(TS. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Malaysia Marine Department
14th August 2026