MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PO BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN

PENINSULAR NOTICE TO MARINERS NTM 163(T)/ 2026

Telephone : 03-3162 9797 | Email : kpgr@marine.gov.my | Website : http://www.marine.gov.my

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 5, MAL 645
BA 3446

UNDERWATER CABLE REPAIR OPERATION
SOUTH CHINA SEA

Mariners are advised that underwater cable repair for Asia Pacific Gateway (APG) system segment 1.9 will be carried out by Ben Line Agencies Malaysia Sdn. Bhd in Kuantan waters, Pahang. The details are as follows;

Duration : **17th August – 31st August 2026**

Vessel Involve:

Vessel Name	Call sign	Flag	Remark
Asean Challenger	YDWG3	Indonesia	Cable layer
Ilham 3	9MCO7	Malaysia	Tug Boat

Area involves:

Latitude	Longitude	Label
04° 03.097' N	103° 59.134' E	Fault Location
04° 04.706' N	103° 38.529' E	Point 1
04° 05.351' N	103° 40.412' E	Point 2
04° 02.186' N	104° 14.014' E	Point 3
04° 01.542' N	104° 14.899' E	Point 4
03° 55.344' N	104° 17.984' E	Point 5
03° 54.919' N	104° 18.313' E	Point 6
03° 54.712' N	104° 18.824' E	Point 7
03° 54.580' N	104° 20.733' E	Point 8

Latitude	Longitude	Label
03° 53.545' N	104° 20.669' E	Point 9
03° 53.691' N	104° 18.783' E	Point 10
03° 54.200' N	104° 17.560' E	Point 11
03° 54.835' N	104° 17.049' E	Point 12
04° 00.901' N	104° 14.108' E	Point 13
04° 01.258' N	104° 13.708' E	Point 14
04° 04.269' N	103° 40.467' E	Point 15
04° 03.621' N	103° 38.574' E	Point 16

Above coordinates are referenced to Datum: WGS

Mariners are advised to give wide berth when passing and navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
17th August 2026