



JABATAN LAUT MALAYSIA
MARINE DEPARTMENT MALAYSIA

MSN 51/2011

Ibu Pejabat Laut Semenanjung Malaysia, Peti Surat 12, 42007 Pelabuhan Klang
Tel : 03-33467777, Fax : 03-31685289, E-mail : kpgr@marine.gov.my
Webpage : <http://www.marine.gov.my>

Notis kepada pemilik kapal, agen perkapalan, Nakhoda, pelaut, pengusaha pelabuhan dan industri maritim
Notice to shipowners, ship agents, Masters, seafarers, port operators and the maritime industry

**UNIFIED INTERPRETATION OF SOLAS REGULATION II-1/29 - MECHANICAL, HYDRAULIC
AND ELECTRICAL INDEPENDENCY AND FAILURE DETECTION AND RESPONSE OF
STEERING CONTROL SYSTEMS**

This is to inform the Maritime Community the adoption of the unified interpretation of SOLAS Regulation II-1/29 by Maritime Safety Committee at its 89th session. Shipping Communities are advice to use the interpretation as per Circular from 20th May 2011 when applying the relevant provisions of SOLAS regulation II-1/29.

1. The details of MSC.1/Circ.1398 are set out [APPENDIX 1](#).

Ketua Pengarah Laut/*Director General of Marine*
Tarikh/Date : 1st October 2011