MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA

PENINSULAR NOTICE TO MARINERS NTM 167 (T) / 2026

Telefon: 03-3162 9797 | Emel : kpgr@marine.gov.my | Laman Web : http://www.marine.gov.my

Authority : Director of Marine, Malaysia

Position : Malacca Strait, Port of Tanjung Pelepas

Charts Affected : MAL 5123
BA 2403

PTP NO.10 LIGHT BUOY ALTERED IN POSITION (TEMPORARY)
JOHOR WATERS

Mariners are advised that PTP No. 10 light buoy has been temporarily repositioned to the following position. The details are as follows:

Name : **PTP NO. 10**

Position : **Lat. 01° 19.569' N,**
Long. 101° 33.172' E

Light Characteristic : **Fl.R.5s**

Type of Mark : **Port-hand lateral mark**

Mariners are advised to navigate with caution and keep safe distance from the buoy when in the vicinity. This Notice in force until further notice.

(TS. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Malaysia Marine Department
29th August 2026