MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : http://www.marine.gov.my

PENINSULAR NOTICE TO MARINERS NTM 174(T)/2026

Authority : Director of Marine, Malaysia

Position : Malacca water

Charts Affected : MAL 5 & MAL 532
BA 3946, BA 3947 & BA 1358

PULAU UNDAN LIGHTHOUSE REDUCED POWER
MALACCA STRAIT

Mariners are advised that Pulau Undan Lighthouse is temporarily operating on reduced power and light nominal range has been reduced from 18 nautical miles to 15 nautical miles while an emergency light is in use during navigation light system works. The details are as follows:

Name : Pulau Undan Lighthouse

Position : Lat. 02° 02.900' N
Long. 102° 20.100' E

Elevation : 53 metres

Characteristic : Fl(2).W.15s

Mariners are advised to navigate with caution when in the vicinity.

(TS. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Malaysia Marine Department
13th September 2026