HYDROGRAPHIC OFFICE
MALAYSIA MARINE DEPARTMENT SARAWAK REGION

NOTICE TO MARINERS
(NOTIS PELAUT)

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my

BORNEO NORTH WEST COAST

149/2026(T) – KUALA PALOH TO SIBU, STARBOARD-HAND BUOYS - MISSING

Kuala Paloh to Sibu, Starboard-hand Buoys as follows are reported missing. Mariners are advised to navigate with caution in the vicinity.

1. Position (WGS 84) : 02°25'16.550"N 111°17'25.270"E
   Characteristic : *Fl.G.4s*

2. Position (WGS 84) : 02°24'33.370"N 111°19'28.340"E
   Characteristic : *Fl.G.4s*

3. Position (WGS 84) : 02°23'00.570"N 111°20'14.520"E
   Characteristic : *Fl.G.4s*

Chart : SAR 1450
Source : Malaysia Marine Department, Sarawak Region
Date : 12 October 2026

"BERKHIDMAT UNTUK NEGARA"

[MUHAMAD SAHABULLAH BIN KASIM]
for Director of Marine Sarawak