MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PO. BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN

PENINSULAR NOTICE TO MARINERS NTM 196 / 2026

Telefon: 03-3162 9797 | Emel : kpgr@marine.gov.my | Laman Web : http://www.marine.gov.my

Authority : Director of Marine, Malaysia

Position : Johor waters

Charts Affected : MAL 515
BA 2403

PS-2 LIGHT BUOY RESTORED TO NORMAL JOHOR WATERS

Mariners are advised that PS-2 light buoy has been restored to normal. The details are as follows:

Name	: **PS-2 PORT BUOY**
Position	: **Lat 01˚ 19.741' N, Long. 104˚ 10.260'E**
	(*Datum: WGS-84*)
Light Characteristic	: **FL.R.5s**
Type	: **Port Hand Lateral Mark**

Mariners are advised to navigate with caution in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
13th October 2026