MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA

PENINSULAR NOTICE TO MARINERS NTM 65(T) / 2026

Telefon: 03-3162 9797 | Emel : kpqr@marine.gov.my | Laman Web : http://www.marine.gov.my

Authority : Director of Marine, Malaysia

Position : South China Sea, Johor Waters

Charts Affected : MAL 6134
BA 2403

BC 2 LIGHT BUOY UNLIT
JOHOR WATERS

Mariners are advised that BC 2 light buoy is unlit. The details are as follows:

Name : **BC 2**

Position : **Lat. 01° 26.205' N**
Long. 104° 03.958' E

Light Characteristic : **QK.W**

Description : **Cardinal mark**

Mariners are advised to navigate with caution when in the vicinity.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department
15th April 2026

CANCEL