JABATAN LAUT MALAYSIA
MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PORT KLANG
SELANGOR DARUL EHSAN
MALAYSIA

Tel : 603-3346 7777
Faks : 603-3168 5289
Laman Web : www.marine.gov.my

SABAH NOTICE TO MARINERS - NTM 52 (T) / 2024

Authority	: Director of Marine, Malaysia
Position	: Sabah Waters, Malaysia
Charts Affected	: MAL 8617 BA 25786

OUTER BAR BOUY MISSING AT SANDAKAN WATERS

Mariners are informed that Outer Bar bouy at Sandakan Waters is reported missing. Detail are as follows;

Name	: Outer Bar bouy
Position	: Lat. 05° 58.917' N
	Long. 118° 14.650' E
Light Characteristics	: F1 W 10s 5M

Mariners are advised to navigate with caution when in the vicinity.

(MUHHAMMAD NASHRUL BIN MUHAMMAD NAZRI)
For The Director of Marine
Malaysia Marine
Department
12th December 2024