HYDROGRAPHIC OFFICE
MALAYSIA MARINE DEPARTMENT SARAWAK REGION

NOTICE TO MARINERS
(NOTIS PELAUT)

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my

BORNEO NORTH WEST COAST

171/2025(T) - STARBOARD LATERAL MARK SIP5 BUOY, SAMALAJU PORT RE-ESTABLISHED

Starboard Lateral Mark SIP5 Buoy, Samalaju Port has been re-established and NTM 207/2024(T) is hereby cancelled.

Position (WGS 84)	: 03°35'39.600"N 113°17'41.500"E
Characteristic	: *Fl. 5s*
Charts	: SAR 501 & SAR 5001
Source	: Marine Department Malaysia, Sarawak Region
Date	: 3rd November 2025

"BERKHIDMAT UNTUK NEGARA"

[MUHAMAD SAHABULLAH BIN KASIM]
for Director of Marine Sarawak