HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK

NOTICE TO MARINERS
(NOTIS PELAUT)

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my

BORNEO NORTH WEST COAST

175/2024(T) – LEBAAN SPECIAL MARK BUOY - MISSING

Lebaan Special Mark Buoy at position 02°17'15.565"N 111°42'14.436"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 2, SAR 5 & SAR 1441
Source : Sarawak Region Marine Department
Date : 11th October 2024

"BERKHIDMAT UNTUK NEGARA"

[RADUAN BIN SERAP]
For Director of Marine Sarawak