HYDROGRAPHIC OFFICE
MALAYSIA MARINE DEPARTMENT SARAWAK REGION

NOTICE TO MARINERS
(NOTIS PELAUT)

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my

BORNEO NORTH WEST COAST

207/2024(T) - STARBOARD LATERAL MARK - SIP5 BUOY, SAMALAJU PORT - MISSING

Starboard Lateral Mark - SIP5 Buoy, Samalaju Port is reported missing. Mariners are advised to navigate with caution in the vicinity.

Charts	: SAR 501 & SAR 5001
Position (WGS 84)	: 03°35'39.600"N 113°17'41.500"E
Source	: Marine Department Malaysia Sarawak Region
Date	: 11th December 2024

"BERKHIDMAT UNTUK NEGARA"

[SYAHRIZAN BIN JILI]
for Director of Marine Sarawak