



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**\*113/2019 – AMEND LIGHT CHARACTERISTIC, SARAWAK WATERS**

The detail are as follows:

1. Amend Batu Camar Buoy light to *Fl(2)6s*, 01°35'57.420"N 110°27'44.940"E.  
( Charts affected: SAR 104 & SAR 1011 )
2. Amend Senari Rear Leading light to *Fl.G(2)6s47m8M*, 01°37'18.743"N  
110°26'49.912"E. ( Charts affected: SAR 101 )
3. Amend No. 3 Tg. Renard Point light to *O.G.16m4M*, 01°35'30.916"N  
110°27'40.301"E. ( Charts affected: SAR 102 )

Mariners are advised to update their affected charts accordingly.

Source : Sarawak Marine Department

Date : 26<sup>th</sup> August 2019

**"BERKHIDMAT UNTUK NEGARA"**

**[ RADUAN BIN SERAP ]**

For Director of Marine Sarawak

**"Ke Arah Negara Kelautan Elektronik"  
"Towards e-Maritime Nation"**



Cert. No: KLR 0403724, KLR0403655