



PEKELILING PELABUHAN NO.26/2019
PORT CIRCULAR NO. 26/2019

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN
TO : GENERAL SHIPPING COMMUNITY

TARIKH : 5 September 2019
DATE : 05th Septembert 2019

CARTA BERKAITAN : MAL 5410
(RELEVANT CHART)

PELAMPUNG PANDU ARAH (STARBOARD HAND LATERAL MARK) G.F1(2)G.5s NO.2 BAGAN DATUK

Masyarakat perkapalan adalah di maklumkan bahawa satu pelampung pandu hanyut dari lokasi dan maklumat adalah seperti berikut;

Nama : G.F1(2)G.5s NO.2
Koordinat Asal : Lat 04° 03.36' U Long 100° 41.33' T
Koordinat Terkini : Pantai Teluk Segadas
Jenis : Bouy Starboard Hijau

Semua pelaut dan vesel dinasihatkan hendaklah berhati-hati ketika belayar berhampiran kawasan tersebut.

' G.F1(2)G.5s NO.2 (STARBOARD HAND LATERAL MARK) LIGHTBUOY BAGAN DATUK

The Shipping Community is hereby informed that one lightbuoy has drifted away from its location and the details as below: -

Name : G.F1(2)G.5s NO.2
Previous Location : Lat 04° 03.36' U Long 100° 41.33' T
Current Location : Teluk Segadas Beach
Type : Starboard Hand Lateral Mark Bouy

All mariners and vessels are advised to be cautious while operating at the vicinity concerned.

(RAMLI BIN SHARIFF)
b.p Pengarah Laut Wilayah Utara
Director of Marine Northern Region