



JABATAN LAUT MALAYSIA
Pejabat Laut Lumut
Tingkat 3, Bangunan Persekutuan
Jalan Kayu Manis
32040 SERI MANJUNG
PERAK DARUL RIDZUAN

Telefon : 05-688 7595
Faks : 05-688 7594
Email : pplum@marine.gov.my
Laman Web : www.marine.gov.my

PEKELILING PELABUHAN NO.29/2019
PORT CIRCULAR NO. 29/2019

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN
TO : GENERAL SHIPPING COMMUNITY

TARIKH : 26 September 2019
DATE : 26th September 2019

CARTA BERKAITAN : MAL 5425
(RELEVANT CHART)

LAMPU PELAMPUNG PANDU ARAH DAN 'BEACON' PULAU KATAK TIDAK BERFUNGSI

Masyarakat perkapalan adalah dimaklumkan bahawa terdapat lampu pelampung pandu arah dan 'beacon' yang tidak berfungsi seperti di kedudukan berikut:

1. Buoy 4 - 04° 09.204' N 100° 34.423' E
2. Fairway Buoy - 04° 08.920' N 100° 32.884' E
3. Beacon Pulau Katak - 04° 09.359' N 100° 37.148' E

Semua pelaut dan vesel dinasihatkan hendaklah berhati-hati ketika belayar berhampiran kawasan tersebut.

' LIGHTBUOY AND BEACON LIGHT NOT FUNCTION

The Shipping Community is hereby informed that light buoy and beacon light has not functioning at location and the details as below: -

1. Buoy 4 - 04° 09.204' N 100° 34.423' E
2. Fairway Buoy - 04° 08.920' N 100° 32.884' E
3. Beacon (Pulau Katak) - 04° 09.359' N 100° 37.148' E

All mariners and vessels are advised to be cautious while operating at the vicinity concerned.

(RAMLI BIN SHARIFF)
b.p Pengarah Laut Wilayah Utara
Director of Marine Northern Region