



**HYDROGRAPHIC OFFICE  
SARAWAK MARINE DEPARTMENT**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422  
Website : [www.jls.gov.my](http://www.jls.gov.my)



---

**BORNEO NORTH WEST COAST**

**34/2009(T) - KUALA BARAM, CHANNEL BUOY NO. 2 - MISSING**

Kuala Baram, Miri, Channel Buoy No.2, *FL.R.4s* at position  $04^{\circ} 35' 45''.002 N$ ,  $113^{\circ} 58' 03''.004 E$  has been reported missing.

2. Mariners are advised to take extreme caution when navigating in the area.

Chart : SAR 421  
Source : Sarawak Marine Department  
Date : 4<sup>th</sup> May 2009

**"BERKHIDMAT UNTUK NEGARA"**

**[SARKAWI BIN NUMAN]**  
For Director of Marine Sarawak