



**HYDROGRAPHIC OFFICE
SARAWAK MARINE DEPARTMENT**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422
Website : www.jls.gov.my



BORNEO NORTH WEST COAST

6/2009(T) - BINTULU PORT, BUOYS - MISSING

The following buoys are reported missing:

Number / Name	Light Characteristic	Position
a. Buoy No. 5,	Fl.G. 5s	03° 15' 49".244 N, 113° 01' 12".592 E
b. Buoy G,	Fl.G. 5s,	03° 15' 20".537 N, 113° 01' 40".547 E
c. Buoy L,	Fl.R. 5s,	03° 15' 17".668 N, 113° 02' 37".354 E

2. Mariners are advised to take extreme caution when navigating in the area.

Chart : SAR 4001

Source : Sarawak Marine Department

Date : 19th January 2009

"BERKHIDMAT UNTUK NEGARA"

[SARKAWI BIN NUMAN]

For Director of Marine Sarawak