



HYDROGRAPHIC OFFICE  
SARAWAK MARINE DEPARTMENT

NOTICE TO MARINERS  
(NOTIS PELAUT)

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422  
Website : www.jls.gov.my



BORNEO NORTH WEST COAST

\*50/2010 – KUALA RAJANG AND KUALA PALOH – NAVIGATIONAL BUOYS -  
ESTABLISHED

1. Tanjung Manis, Kuala Rajang, Sarawak

Insert – Porthand buoy, *FL.R.4s*, at position  $02 \rightarrow 07' 00''.07 N$ ,  $111 \rightarrow 18' 04''.68 E$

2. Kuala Paloh, Sarawak

Insert – i) Starboard buoy, *FL.G.4s*, at position  $02 \rightarrow 26' 53''.81 N$ ,  $111 \rightarrow 14' 43''.77 E$   
ii) Porthand buoy, *FL.R.4s*, at position  $02 \rightarrow 27' 29''.61 N$ ,  $111 \rightarrow 15' 00''.92 E$   
iii) Starboard buoy, *FL.G.4s*, at position  $02 \rightarrow 25' 16''.55 N$ ,  $111 \rightarrow 17' 25''.27 E$   
iv) Starboard buoy, *FL.G.4s*, at position  $02 \rightarrow 24' 33''.37 N$ ,  $111 \rightarrow 19' 28''.34 E$   
v) Starboard buoy, *FL.G.4s*, at position  $02 \rightarrow 23' 00''.57 N$ ,  $111 \rightarrow 20' 14''.52 E$

3. Mariners are advised to update their affected charts accordingly.

Charts : SAR 1440 & SAR 1450  
Source : Sarawak Sarawak Rivers Board  
Date : 14<sup>th</sup> October 2010

"BERKHIDMAT UNTUK NEGARA"

[SARKAWI BIN NUMAN]  
For Director of Marine Sarawak