



**JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA**

NOTICE TO MARINERS

NTM 84/1999

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.

Tel: 03 3695100

Fax: 03 3685289

E-mail: kpgr@marine.gov.my

Web site: <http://www.marine.gov.my>

Authority : Director of Marine, Peninsular Malaysia

Position : Johore Straits, Malaysia

Charts Affected : BA 2570.2587,3833

TANJUNG PELEPAS PORT-LIGHT BUOYS ESTABLISHED

1. Mariners are advised that 11 set of lightbuoys have been established in Tanjung Pelepas Port to mark the fairway as follows :-

Buoy No	Type	Positions		Characteristics
No 1	Stbd	LAT. 01° 15'50.99 N	LONG. 103° 32'43.86 E	Fl.G2s
No 2	Port	LAT. 01° 15'53.44 N	LONG. 103° 32'36.02 E	Fl.R2s
No 3	Stbd	LAT. 01° 16'48.99 N	LONG. 103° 33'00.19 E	Fl.(2)G10s
No 5	Stbd	LAT. 01° 17'47.63 N	LONG. 103° 33'16.48 E	Fl.(3)G15s
No 7	Stbd	LAT. 01° 18'45.97 N	LONG. 103° 33'32.74 E	QG
No 8	Port	LAT. 01° 18'47.62 N	LONG. 103° 33'24.71 E	QR
No 9	Stbd	LAT. 01° 19'19.30 N	LONG. 103° 33'33.42 E	Fl.G5s
No 11	Stbd	LAT. 01° 19'51.69 N	LONG. 103° 33'26.06 E	Fl.(2)G10s
No 12	Port	LAT. 01° 19'48.72 N	LONG. 103° 33'18.53 E	Fl.(2)R10s
No 13	Stbd	LAT. 01° 20'54.38 N	LONG. 103° 33'01.14 E	QG
SP 1	Special	LAT. 01° 22'23.80 N	LONG. 103° 32'17.97 E	Fl.Y2s

(Capt. Nazri Bin Abu Hassan)

for Director of Marine

Peninsular Malaysia.

14 October 1999