



JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA



NOTICE TO MARINERS NTM 68(T)/2006

MS ISO 9001
Approval Cert. No : 403591 A
Approval Cert. No : 403591 C
Approval Cert. No : 403591 D

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.
 Tel: 03 33467777 Fax: 03 31685020 E-mail: kpgr@marine.gov.my Web site: <http://www.marine.gov.my>

Authority : Director of Marine, Peninsular Malaysia
 Position : Sungai Johor
 Charts Affected : MAL 6134 & BA 4043

TEMPORARY NAVIGATIONAL CHANNEL
IN SUNGAI JOHOR

Mariners are advised that a temporary navigational channel has been established in Sungai Johor within a working area to coincide with the construction of a bridge across Sungai Johor.

The said working area are bounded by the following coordinates:

WGS 84

	Latitude North	Longitude East
A	01° 32.12'	104° 00.87'
B	01° 31.59'	104° 00.98'
C	01° 31.76'	104° 01.82'
D	01° 32.29'	104° 01.71'

The temporary navigational channel are marked by 4 lateral mark buoys with description and position as follows :

	DESCRIPTION OF BUOYS	WGS 84 POSITIONS
N1	Red Can Buoy with Topmark	01° 32.10' N 104° 01.25' E

N2	Green Conical Buoy with Topmark	01° 32.15' N 104° 01.33' E
S1	Red Can Buoy with Topmark	01° 31.77' N 104° 01.32' E
S2	Green Conical Buoy with Topmark	01° 31.79' N 104° 01.40' E

Mariners are advised to keep clear of the working area and to use the temporary navigation channel whilst transiting the working area giving particular regard to working vessels in the vicinity.

(AZMI BIN HARUN)
for The Director General,
Marine Department Peninsular Malaysia.

22 December 2006