



JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA



NOTICE TO MARINERS

NTM 64/2008

MS ISO 9001

Approval Cert. No : 403591 A
Approval Cert. No : 403591 C
Approval Cert. No : 403591 D

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.
 Tel: 03 33467777 Fax: 03 31685020 E-mail: kpgr@marine.gov.my Web site: <http://www.marine.gov.my>

Authority : Director of Marine, Peninsular Malaysia
 Position : Pulau Perhentian, Terengganu
 Charts Affected : MAL 664 & BA 771

SUBMARINE WATER PIPELINE ESTABLISHED
PULAU PERHENTIAN, TERENGGANU

Mariners are advised that a submarine water pipeline has been established from Bukit Bubus, Tembila, Besut to Tg. Batu Panji-Panji, Pulau Perhentian Kecil at the following coordinates:

Location (WGS 84) :

PT. NO	Coordinates	
P1 Bukit Bubus	05° 47.19699' N	102° 37.19630' E
P2	05° 47.24719' N	102° 37.27962' E
P3	05° 47.25484' N	102° 37.27604' E
P4	05° 47.45481' N	102° 37.39002' E
P5	05° 47.56533' N	102° 37.45924' E
P6	05° 47.77657' N	102° 37.61145' E
P7	05° 47.84248' N	102° 37.65949' E
P8	05° 47.94334' N	102° 37.72162' E
P9	05° 48.05181' N	102° 37.81493' E
P10	05° 48.21360' N	102° 37.93239' E
P11	05° 48.33583' N	102° 38.04499' E
P12	05° 48.47372' N	102° 38.14539' E
P13	05° 48.63822' N	102° 38.27019' E
P14	05° 48.81124' N	102° 38.40078' E
P15	05° 48.99582' N	102° 38.53326' E
P16	05° 49.11184' N	102° 38.62453' E
P17	05° 49.20207' N	102° 38.69259' E
P18	05° 49.31688' N	102° 38.77443' E
P19	05° 49.44999' N	102° 38.86883' E
P20	05° 49.52367' N	102° 38.93387' E
P21	05° 49.62590' N	102° 39.01503' E
P22	05° 49.77100' N	102° 39.10947' E
P23	05° 49.87577' N	102° 39.18607' E
P24	05° 50.06992' N	102° 39.34466' E
P25	05° 50.15201' N	102° 39.41429' E

P26	05° 50.30911' N	102° 39.53099' E
P27	05° 50.43750' N	102° 39.62989' E
P28	05° 50.57578' N	102° 39.74184' E
P29	05° 50.73618' N	102° 39.84646' E
P30	05° 50.81827' N	102° 39.91767' E
P31	05° 50.88721' N	102° 39.97053' E
P32	05° 50.97304' N	102° 40.03686' E
P33	05° 51.09083' N	102° 40.10815' E
P34	05° 51.24295' N	102° 40.23732' E
P35	05° 51.44175' N	102° 40.39385' E
P36	05° 51.52838' N	102° 40.51046' E
P37	05° 51.60477' N	102° 40.64289' E
P38	05° 51.67725' N	102° 40.76222' E
P39	05° 51.75873' N	102° 40.88782' E
P40	05° 51.90324' N	102° 41.11413' E
P41	05° 51.98690' N	102° 41.25165' E
P42	05° 52.00755' N	102° 41.29280' E
P43	05° 52.14063' N	102° 41.48391' E
P44	05° 52.18787' N	102° 41.53750' E
P45	05° 52.24549' N	102° 41.67721' E
P46	05° 52.29186' N	102° 41.76331' E
P47	05° 52.33077' N	102° 41.80282' E
P48	05° 52.40682' N	102° 41.92193' E
P49	05° 52.47965' N	102° 42.08059' E
P50	05° 52.52800' N	102° 42.16397' E
P51	05° 52.61330' N	102° 42.31341' E
P52	05° 52.69315' N	102° 42.43253' E
P53	05° 52.78277' N	102° 42.56463' E
P54	05° 52.86968' N	102° 42.69999' E
P55	05° 52.91858' N	102° 42.79746' E
P56	05° 52.99787' N	102° 42.90140' E
P57	05° 53.08751' N	102° 43.06276' E
P58	05° 53.15322' N	102° 43.14884' E
P59	05° 53.31945' N	102° 43.42823' E
P60	05° 53.43134' N	102° 43.60203' E
P61	05° 53.48616' N	102° 43.64132' E
P62	05° 53.61206' N	102° 43.70156' E
P63	05° 53.64515' N	102° 43.69395' E
P64 Batu Panji-Panji, Pulau Perhentian Kecil	05° 53.71696' N	102° 43.66172' E

Mariners are hereby notified that anchoring in the vicinity of the areas of 200 meters on both sides along the said water pipeline is strictly prohibited.

(SYAHRIZAN BIN JILI)

for The Director General,
Marine Department Peninsular Malaysia.
16 September 2008