



**JABATAN LAUT SEMENANJUNG MALAYSIA,
IBU PEJABAT LAUT WILAYAH TIMUR,
JALAN HILIRAN,
20300 KUALA TERENGGANU.
TERENGGANU DARUL IMAN.**

Telefon : 09 - 622 1471/ 9473/9478 Emel : plwtm@marine.gov.my
Faks : 09 - 623 3676 Laman Web : <http://www.marine.gov.my>



MS ISO 9001
Approval Cert. No : 403591 A
Approval Cert. No : 403591 C
Approval Cert. No : 403591 D

**PEKELILING PELABUHAN BIL (1/2005)
PORT CIRCULAR NO. (1/2005)**

DARIPADA : PENGARAH LAUT WILAYAH TIMUR
FROM : DIRECTOR OF MARINE EASTERN REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN PERKAPALAN
DAN MASYARAKAT PERKAPALAN AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENT AND THE
GENERAL SHIPPING COMMUNITY

TARIKH : 4 Januari 2005
DATED : 4 January 2005

BIKON TG. BERHALA NO 2 TIDAK BERFUNGSI / TG. BERHALA NO 2 BEACON MALFUNCTIONED

KETERANGAN:

Adalah dimaklumkan bahawa Bikon Tg. Berhala No.2 di Pelabuhan Kemaman telah tidak berfungsi.

Ciri-ciri bikon tersebut seperti berikut :

Kedudukan : 04° 13' 35'' U
103° 29' 14.00''T
Fl. R 5 11M 8n.m

PERINGATAN :

Masyarakat perkapalan yang belayar berhampiran dengannya hendaklah belayar dengan berhati-hati.

(ROSSID BIN MUSA)
Pengarah Laut Wilayah Timur,
Kuala Terengganu

DETAILS:

This is to notify that Tg. Berhala Beacon No. 2 at Kemaman Port is malfunctioned.

Beacon characteristic as below :

*Position : 04° 13' 35'' N
103° 29' 14.00''E
Fl. R 5 11M 8n.m*

CAUTION :

Mariners are advised to navigate with caution when entering the area.

Director,
Marine Department Eastern Region,
Kuala Terengganu