



**JABATAN LAUT SEMENANJUNG MALAYSIA,
IBU PEJABAT LAUT WILAYAH TIMUR,
JALAN HILIRAN,
20300 KUALA TERENGGANU.
TERENGGANU DARUL IMAN.**

Telefon : 09 - 622 1471/ 9473/9478 Emel : plwtm@marine.gov.my
Faks : 09 - 623 3676 Laman Web : <http://www.marine.gov.my>



MS ISO 9001: 2000
Approval Cert. No : 403591 A
Approval Cert. No : 403591 C
Approval Cert. No : 403591 D

**PEKELILING PELABUHAN BIL 10/2005
(PORT CIRCULAR NO 10/2005)**

DARIPADA : PENGARAH LAUT WILAYAH TIMUR
FROM : *DIRECTOR OF MARINE EASTERN REGION*

KEPADA : SEMUA NAKHODA KAPAL, PELAUT DAN MASYARAKAT NELAYAN
TO : *ALL SHIP MASTERS, MARINERS AND FISHING COMMUNITY*

TARIKH : 29 Mac 2005
DATED : *29 March 2005*

**STARBOARD HAND OUTER BUOY KUALA SUNGAI KUANTAN HILANG / STARBOARD HAND OUTER
BUOY AT THE MOUTH OF SUNGAI KUANTAN MISSING**

Keterangan:

Adalah dimaklumkan bahawa Starboard Hand Outer Buoy dikedudukan Latitud 03° 47' 14'' U dan Longitude 103° 21' 24'' T di Kuala Sungai Kuantan telah hilang.

Peringatan :

Masyarakat perkapalan hendaklah belayar dengan berhati-hati apabila memasuki kawasan.

Details:

This is to notify that Starboard Hand Outer Buoy at position Latitude 03° 47' 14'' N and Longitude 103° 21' 24'' E in Sungai Kuantan river mouth was missing.

Caution :

Mariners are advised to navigate with caution when entering the area.

(ROSSID BIN MUSA)
Pengarah Laut Wilayah Timur,
Kuala Terengganu

Director,
Marine Department Eastern Region,
Kuala Terengganu