



**JABATAN LAUT SEMENANJUNG MALAYSIA,  
IBU PEJABAT LAUT WILAYAH TIMUR,  
JALAN HILIRAN,  
20300 KUALA TERENGGANU.  
TERENGGANU DARUL IMAN.**

Telefon : 09 - 622 1471/ 9473/9478 Emel : [plwtm@marine.gov.my](mailto:plwtm@marine.gov.my)  
Faks : 09 - 623 3676 Laman Web : <http://www.marine.gov.my>



**MS ISO 9001**  
*Approval Cert. No : 403591 A*  
*Approval Cert. No : 403591 C*  
*Approval Cert. No : 403591 D*

**PEKELILING PELABUHAN BIL (11/2005)  
PORT CIRCULAR NO. (11/2005)**

DARIPADA : PENGARAH LAUT WILAYAH TIMUR  
*FROM* : *DIRECTOR OF MARINE EASTERN REGION*

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN PERKAPALAN  
DAN MASYARAKAT PERKAPALAN AMNYA  
*TO* : *ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENT AND THE  
GENERAL SHIPPING COMMUNITY*

TARIKH : 9 Mei 2005  
*DATED* : *9 May 2005*

**BIKON PULAU BERHALA TIDAK BERFUNGSI / PULAU BERHALA BEACON MALFUNCTIONED**

**KETERANGAN:**

Adalah dimaklumkan bahawa Bikon Pulau Berhala di Pahang telah tidak berfungsi.

Ciri-ciri bikon tersebut seperti berikut :

Kedudukan : 03° 14' 42.00'' U  
103° 39' 30.00'' T  
Fl.(2)W.5s 33M.10 n.m

**PERINGATAN :**

Masyarakat perkapalan yang belayar berhampiran dengannya hendaklah belayar dengan berhati-hati.

**(ROSSID BIN MUSA)**  
Pengarah Laut Wilayah Timur,  
Kuala Terengganu

**DETAILS:**

*This is to notify that Pulau Berhala Beacon at Pahang is malfunctioned.*

*Beacon characteristic as below :*

*Position : 03° 14' 42.00'' N  
103° 39' 30.00'' E  
Fl.(2)W.5s 33M.10 n.m*

**CAUTION :**

Mariners are advised to navigate with caution when entering the area.

**Director,**  
**Marine Department Eastern Region,**  
**Kuala Terengganu**