



**JABATAN LAUT SEMENANJUNG MALAYSIA,  
IBU PEJABAT LAUT WILAYAH TIMUR,  
JALAN HILIRAN,  
20300 KUALA TERENGGANU.  
TERENGGANU DARUL IMAN.**

Telefon : 09 - 622 1471/ 9473/9478 Emel : [plwtm@marine.gov.my](mailto:plwtm@marine.gov.my)  
Faks : 09 - 623 3676 Laman Web : <http://www.marine.gov.my>



**MS ISO 9001**  
Approval Cert. No : 403591 A  
Approval Cert. No : 403591 C  
Approval Cert. No : 403591 D

**PEKELILING PELABUHAN BIL  
13/2005**

DARIPADA PENGARAH LAUT WILAYAH  
TIMUR  
KEPADA SEMUA NAKHODA KAPAL,  
PELAUT, PEMILIK & AGEN  
PERKAPALAN  
DAN MASYARAKAT  
PERKAPALAN AMNYA

TARIKH 31 Mei 2005

**BOYA NORTH CARDINAL MARK  
TELAH HANYUT**

**KETERANGAN:**

Adalah dimaklumkan bahawa Boya North Cardinal Mark di kedudukan Lat: 04° 14' 00" U Long: 103° 27' 17" T di Kuala Kemaman telah hanyut dan di dikeluarkan dari kedudukan.

**PERINGATAN**

Masyarakat perkapalan yang belayar berhampiran dengannya hendaklah belayar dengan berhati-hati.

**(ROSSID BIN MUSA)**  
Pengarah Laut Wilayah Timur,  
Kuala Terengganu

**PORT CIRCULAR NO  
13/2005**

FROM DIRECTOR OF MARINE EASTERN  
REGION  
TO ALL SHIP MASTERS, MARINERS,  
SHIP OWNSERS & AGENTS AND  
THE GENERAL SHIPPING  
COMUNITY

DATE 31 Mei 2005

**NORTH CARDINAL MARK HAD  
DRIFTED**

**DETAILS:**

*This is to notify that the North Cardinal Mark Buoy at position Lat: 04° 14' 00" N Long: 103° 27' 17" E at Kuala Kemaman was drifted and had been removed from its position.*

**DETAILS**

*Mariners are advised to navigate with caution when entering the area.*

**Director,  
Marine Department Eastern Region,  
Kuala Terengganu**