



JABATAN LAUT SEMENANJUNG MALAYSIA
Pejabat Laut Wilayah Persekutuan Labuan,
Peti Surat 81005, 87008 Wilayah Persekutuan Labuan.

Telefon : +6 087 – 413 511 Emel : pilwplbn@marine.gov.my
Faks : +6 087 – 413 515 Laman Web : www.marine.gov.my

PEKELILING PELABUHAN PORT CIRCULAR

NO. 08/2007



MS ISO 9001
Approval Cert. No : 403591 A
Approval Cert. No : 403591 C
Approval Cert. No : 403591 D

LIGHT BUOY (EAST CH. NO.1 (G) RESUMED OPERATION

BOYA BERLAMPU (EAST CH. NO.1 (G) BEROPERASI SEMULA

Daripada : Pengarah Laut
From : *Director of Marine*
Kepada : Masyarakat Perkapalan / Pengguna-Pengguna Pelabuhan
To : *Shipping Community/ Ports User*
Tarikh : 27hb February, 2007
Date : *27th February, 2007*
Carta Berkaitan : BA 947, MAL 8518
Effective Chart

Masyarakat perkapalan dimaklumkan bahawa boya berlampu (East Ch. No.1 (G) telah beroperasi semula.

Shipping community is hereby notified that light buoy (East Ch. No.1 (G) resumed operation

Nama : East Ch. No.1 (G)
Kedudukan : Lat. 05⁰ 18.20' Utara
Long. 115⁰ 16.94' Timur
(Timbalai Datum)

Name : (East Ch. No.1 (G)
Position : Lat. 05⁰ 18.20' North
Long. 115⁰ 16.94' East
(Timbalai Datum)

Sifat lampu : FL (G) 5s 4M

Light Characteristic : FL.(G) 5s 4M

Pekeliling Pelabuhan No. 05 Tahun 2007 dibatalkan.

Port Circular No. 05 Year 2007 hereby cancelled.

(RUSLAN BIN HUSIN)
for Director of Marine
Marine Department of Labuan Federal Territory

SA 12

Shipping community is hereby notified that light buoy (East Ch. No.1 (G) resumed operation

Name : (East Ch. No.1 (G)
Position : Lat. 05⁰ 18.20' North
Long. 115⁰ 16.94' East
(*Timbalai Datum*)

Light Characteristic : FL.(G) 5s 4M

Port Circular No. 05 Year 2007 hereby cancelled.

Kepada :- Operator Wireless
Sila siarkan 'Navigational warning' ini melalui siaran NAVTEX sehingga
02/03/2007