



**JABATAN LAUT SEMENANJUNG MALAYSIA
PEJABAT PENGARAH LAUT WILAYAH SELATAN
TANJUNG PELEPAS, 81560 GELANG PATAH
JOHOR DARUL TAKZIM**

Telefon : 07- 507 2313 Emel : pjlwst@marine.gov.my
Faks : 07- 507 3679 Laman Web : http://www.marine.gov.my



MS ISO 9002
Approval Cert. No : 403591 F

PEKELILING PELABUHAN NO. 02/2005
PORT CIRCULAR NO. 02/2005

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : *DIRECTOR OF MARINE SOUTHERN REGION*

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
TO : *ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS*
AND THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 10 MAC 2005/ 10 MARCH 2005

KERJA-KERJA PENGOREKKAN DI TG. BIN, PONTIAN, JOHOR.

Ini adalah untuk memaklumkan bahwa kerja-kerja pengorekkan yang merupakan sebahagian daripada pembinaan sebuah janakuasa arang batu akan dijalankan di Tg. Bin, Pontian, Johor. Satu kawasan kerja telah diwujudkan yang bersempadankan koordinat-koordinat seperti berikut :

WGS 84

	Latitud Utara	Longitud Timur
A	01° 19.71'	103° 33.15'
B	01° 19.20'	103° 33.15'
C	01° 19.20'	103° 32.67'
D	01° 19.98'	103° 32.67'

Tempoh : Anggaran selama 5 bulan dari tarikh pekeliling ini.

Waktu Kerja : 24 jam setiap hari

Vesel-vesel Yang Terlibat:

Barj Korek Cekau
Barj Atas Rata
Bot Penolak
Barj Buangan

DREDGING WORKS AT TG. BIN, PONTIAN, JOHOR.

This is to notify that dredging works forming part of the construction of a coal-fired power station will be carried out at Tg. Bin, Pontian, Johor. A working area has been established bounded by the following coordinates :

WGS 84

	Latitude North	Longitude East
A	01° 19.71'	103° 33.15'
B	01° 19.20'	103° 33.15'
C	01° 19.20'	103° 32.67'
D	01° 19.98'	103° 32.67'

Duration : *Approximately 5 months from the date of this circular.*

Working Hours : 24 hours daily

Vessels Involved :

Grab Dredge Barge
Flat Top Barges
Pusher Tugs
Hopper Barges

PEKELILING PELABUHAN NO. 02/2005

PORT CIRCULAR NO. 02/2005

PERHATIAN

Semua pelaut adalah dinasihati untuk menjauhi kawasan kerja tersebut dan belayar dengan lebih berhati-hati apabila menghampiri kawasan kerja ini kerana vesel-vesel kerja akan beroperasi keluar dan masuk disekitar kawasan kerja tersebut.

Carta Terlibat: MAL 5128, MAL 5123, BA 4038

CAUTION

All mariners are advised to keep clear of the working area and to navigate with extra caution when approaching this area as working vessels will operate in and out in the vicinity of the said working area.

Charts affected : MAL 5128, 5123, BA 4038

Sekian, terima kasih.

“BERKHIDMAT UNTUK NEGARA”

Saya yang menurut perintah,

(HAZMAN BIN HUSSEIN)

Pengarah Laut / *Director of Marine*
Wilayah Selatan / Southern Region