



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 200(T)/2021

Telefon               : 03-3346 7777      Emel                 : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili            : 03-3168 5289      Laman Web       : <http://www.marine.gov.my>

---

Authority             : Director of Marine, Malaysia

Position             : South China Sea

Charts Affected     : MAL 635  
                          BA 3446 & BA 1379

---

### KUANTAN PORT LEADING LIGHT 311° 04 REAR LIGHT BEACON RESTORED TO NORMAL KUANTAN PORT, PAHANG

---

Mariners are advised that Kuantan Port Leading Light 311° 04 Rear Light Beacon has been restored to normal.

Name                 : Kuantan Port Leading Light 311° 04 Rear

Position             : Lat.    03° 58.940' N  
                          Long. 103° 25.490' E

Light Characteristic : OC.G.5s

This notice cancels NTM 188(T)/2021.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
29<sup>th</sup> October 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602