



**JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT WILAYAH UTARA
JALAN AKUARIUM
11700 GELUGOR
PULAU PINANG**

Tel : 604-6579636
Faks : 604-6575521
Laman Web : www.marine.gov.my

**PEKELILING PELABUHAN NO.2/2018
PORT CIRCULAR NO. 2/2018**

DARIPADA : PENGARAH LAUT WILAYAH UTARA
FROM : DIRECTOR OF MARINE NORTHERN REGION

KEPADA : MASYARAKAT PERKAPALAN
TO : GENERAL SHIPPING COMMUNITY

TARIKH : 26 Januari 2018
DATE : 26 Januari 2018

CARTA BERKAITAN : MAL 5529
RELEVANT CHART

PEMASANGAN BOYA NORTH CARDINAL MARK

Masyarakat perkapalan adalah dimaklumkan pemasangan boya north cardinal mark di tempat Tandarah Suar Aston di laporkan hilang di kedudukan ; *Lat : 05°24'35"N ; Long : 100°20'68"E* di Pelabuhan Pulau Pinang.

Semua vesel diminta untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan tandarah suar tenggelam.

INSTALLATION NORTH CARDINAL MARK BUOYS

Mariners are informed that the Installation of the North Cardinal Mark buoys in the Aston Observatory is reportedly missing in position, Lat : 05°24'35"N ; Long : 100°20'68"E at Port of Penang.

Vessel are advised to navigate with extreme when navigating in vicinity and give wide berth as possible from beacon wreckage

(KAPT ABDUL SAMAD BIN SHAIK OSMAN)
Pengarah Laut Wilayah Utara
Director Of Marine Northern Region

“Ke Arah Negara Kelautan Elektronik”
“Towards e-Maritime Nation”

