



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

29/2022(T) – MUARA LASSA - OUTER BUOY - MISSING

The Outer Buoy, *Fl.G.3s* at position 02° 52' 25.640" N, 111° 24' 30.605" E is reported missing.

2. Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 5, SAR 15 & SAR 190

Source: Sarawak Marine Department

Date : 2nd March 2022

" BERKHIDMAT UNTUK NEGARA "

[MUHAMAD SAHABULLAH BIN KASIM]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600