



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 209/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Lumut Port

Charts Affected : MAL 5425
 BA 792

WEST CARDINAL LIGHT BUOY PERMANENTLY WITHDRAWN LUMUT PORT

Mariners are advised that West Cardinal Light Buoy have been permanently withdrawn.
The details are as follows:

Name	:	West Cardinal light Bouy
Position	:	Lat 04° 16.379' N Long 100° 34.016' E
Elevation	:	3.5 meters
Range of Light	:	5 Nm
Light Character	:	FL (9) W.15S
Description	:	West Cardinal Mark

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Marine Department Malaysia.
30th December 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602