



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

13/2021(T) - PIPELINE MAINTENANCE AND REPAIR WORKS AT PL429 BOKOR FIELD AND PL430 TEMANA FIELD, OFFSHORE SARAWAK

Mariners are advised that PETRONAS Carigali Sdn. Bhd. will carry out pipeline maintenance and repair works at PL429 Bokor Field and PL430 Temana Field, offshore Sarawak on or about 29th January 2021 until 31st July 2021.

2. The coordinate location:

Location	Latitude	Longitude
From BODP-C to BOP-A	4° 32' 48.20" N	113° 37' 46.47" E
	4° 32' 58.26" N	113° 37' 26.79" E
From TEJT-W to TEDP-C	3° 14' 47.74" N	112° 48' 38.80" E
	3° 15' 4.62" N	112° 46' 53.36" E

Above coordinates are referred to WGS 84

3. Vessels involved:

Name	Flag	Length	Breadth
MV PRIDE	Malaysia	130 m	28 m
SOUTHERN STAR	Marshall Island	112 m	24 m
SEALINK 178	Malaysia	84.80 m	22.00 m
PH ABEL	Malaysia	40.12 m	7.80 m
SMS VENTURES	Malaysia	36.63 m	7.80 m

4. All vessels are required to navigate with caution when in vicinity.

Charts : SAR 1, SAR 2, SAR 4, SAR 6, SAR 7 & SAR 401

Source : PETRONAS Carigali Sdn. Bhd.

Date : 01st February 2021

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600