



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

***98/2022 – Y5 BUOY, BINTULU PORT – RESTORED TO NORMAL AND MOVE**

Y5 Buoy, Bintulu Port has been restored to normal and move from 03°15'58.024"N 113°03'50.471"E to 03°15'58.117"N 113°03'50.458"E.

2. Notice 66/2022(T) is hereby cancelled and mariners are advised to update their affected charts accordingly.

Charts : SAR 6, SAR 401, SAR 402 & SAR 4001
Source : Sarawak Region Marine Department
Date : 23rd August 2022

"BERKHIDMAT UNTUK NEGARA"

[RADUAN BIN SERAP]

For Director of Marine Sarawak

“Safer Ships, Secure Ports, Cleaner Seas”



Cert. No: ISO 9001-0047621, ISO 9001-0047600