



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## **NOTICE TO MARINERS      NTM 133/2021**

Telefon               : 03-3346 7777      Emel                 : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili            : 03-3168 5289      Laman Web       : <http://www.marine.gov.my>

---

Authority             : Director of Marine, Malaysia

Position             : South China Sea

Charts Affected     : MAL 635  
                          BA 3446 & BA 1379

---

### **KUANTAN PORT FAIRWAY INNER LIGHT BUOY RESTORED TO NORMAL KUANTAN PORT, PAHANG**

Mariners are advised that Kuantan Port Fairway Inner Light Buoy has been restored to normal.

Name                 : Kuantan Port Fairway Inner Light Buoy

Position             : Lat.    03° 55.520' N  
                          Long. 103° 29.150' E

Light Characteristic : L.FL.10s

This notice cancels NTM 130(T)/2021.

**(RINA MASLINA BINTI BAHARUDIN)**  
for The Director General,  
Marine Department Malaysia.  
29<sup>th</sup> July 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602