



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 18/2021**

Telefon           : 03-3346 7777   Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili       : 03-3168 5289   Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Malacca Strait

Charts Affected   : MAL 5129  
                          BA 2403

---

### **P19 SPECIAL MARK LIGHT BUOY RESTORED TO NORMAL JOHOR WATERS**

---

Mariners are advised that P19 Special Mark Light Buoy has been restored to normal.  
The details are as follows:

Name               : P19 Special Mark  
Position           : Lat.   01° 15.980' N  
                          Long. 103° 34.880' E  
Light Characteristic : Fl.Y.5s

This notice cancels NTM 15(T)/2021.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
10<sup>th</sup> February 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602