



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 06(T)/2021**

Telefon           : 03-3346 7777   Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289   Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : South China Sea

Charts Affected   : MAL 635  
                          BA 1379 & BA 3446

---

### **KUANTAN PORT FAIRWAY INNER LIGHT BUOY DESTROYED KUANTAN PORT, PAHANG**

---

Mariners are advised that Kuantan Port Fairway Inner Light Buoy was destroyed. The details are as follows:

Name                : Kuantan Port Fairway Inner

Position            : Lat.    03° 55.520' N  
                          Long. 103° 29.150' E

Light Characteristic : L.FL.10s

Mariners are advised to navigate with caution in the area.

**(RINA MASLINA BINTI BAHARUDIN)**

for The Director General,  
Marine Department Malaysia.  
15<sup>th</sup> January 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602