



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 08/2021**

Telefon           : 03-3346 7777    Emel               : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Johor Strait

Charts Affected   : MAL 515  
                          BA 2403

---

### **PUTRI SEA ISOLATED DANGER MARK LIGHT BUOY RESTORED TO NORMAL PASIR GUDANG PORT LIMIT**

---

Mariners are advised that Putri Sea Isolated Danger Mark Light Buoy has been restored to normal. The details are as follows:

Name               : Putri Sea Isolated Danger Mark

Position           : Lat.    01° 17.880' N  
                          Long. 104° 07.240' E

Light Characteristic : Fl(2).W.10s

This notice cancels NTM 279(T)/2020.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
19<sup>th</sup> January 2021