



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

***102/2022 – PORT LATERAL MARK - SIP2 BUOY, SAMALAJU PORT - RESTORED TO NORMAL AND MOVE**

Port Lateral Mark - SIP2 Buoy, Samalaju Port has been restored to normal and move from 03°36'42.400"N 113°16'50.600"E to 03°36'42.521"N 113°16'50.753"E.

2. Notice 10/2022(T) is hereby cancelled and mariners are advised to update their affected charts accordingly.

Charts : SAR 501 & SAR 5001
Source : Sarawak Region Marine Department
Date : 23rd August 2022

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

“Safer Ships, Secure Ports, Cleaner Seas”



Cert. No: ISO 9001-0047621, ISO 9001-0047600