



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: [www.marine.gov.my](http://www.marine.gov.my)



**BORNEO NORTH WEST COAST**

**143/2022(T) – STARBOARD LATERAL MARK - SIP1 BUOY, SAMALAJU PORT - MISSING**

Starboard Lateral Mark - SIP1 Buoy at position 03°36'37.100"N 113°16'45.000"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001  
Source : Sarawak Region Marine Department  
Date : 4<sup>th</sup> November 2022

**"BERKHIDMAT UNTUK NEGARA"**

**[ ABANG MOHAMAD BIN ABANG NAILI ]**

For Director of Marine Sarawak

**"Safer Ships, Secure Ports, Cleaner Seas"**



Cert. No: ISO 9001-0047621, ISO 9001-0047600