



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 96(T)/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang waters

Charts Affected : MAL 5300
 BA 3945

SOUTH FAIRWAY LIGHT BUOY UNLIT PORT KLANG WATERS

Mariners are advised that South Fairway Light Buoy unlit.

Name : South Fairway

Position : Lat. 02° 48.999' N
 Long. 101° 14.800' E

Light Characteristic : L. Fl.10s

Mariners are advised to navigate with caution in the area.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
12th July 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602