



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

142/2022(T) – STARBOARD LATERAL MARK - SIP7 BUOY, SAMALAJU PORT – MISSING

Starboard Lateral Mark - SIP7 Buoy at position 03°35'10.700"N 113°18'09.900"E is reported missing. Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001
Source : Sarawak Region Marine Department
Date : 1st November 2022

"BERKHIDMAT UNTUK NEGARA"

[ABANG MOHAMAD BIN ABANG NAILI]

For Director of Marine Sarawak

“Safer Ships, Secure Ports, Cleaner Seas”



Cert. No: ISO 9001-0047621, ISO 9001-0047600