



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

10/2022(T) – PORT LATERAL MARK - SIP2 BUOY, SAMALAJU PORT - MISSING

Port Lateral Mark - SIP2 Buoy at position 03°36'42.400"N 113°16'50.600"E is reported missing. Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 501 & SAR 5001

Source : Sarawak Marine Department

Date : 14th January 2022

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600