



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

***60/2022 - TG PO BUOYS REPOSITIONED**

Mariners are advised that the following buoys have been repositioned as follows:

Buoys	Characteristic	Move from	
		existing position	to new position
Fairway Buoy	Fl. W. 5s	(New)	01°49'05.198"N 110°30'32.401"E
Buoy No. 1	Fl. G. 5s	01°42'24.414"N 110°32'50.210"E	01°48'09.995"N 110°30'49.027"E
Buoy No. 2	Fl. R. 5s	01°48'09.970"N 110°30'59.022"E	01°48'09.970"N 110°30'59.022"E
Buoy No. 3	Fl. G. 5s	01°40'49.865"N 110°32'09.227"E	01°45'14.278"N 110°31'57.991"E
Buoy No. 4	Fl. R. 5s	01°42'19.440"N 110°33'07.412"E	01°45'14.704"N 110°32'07.980"E
Buoy No. 5	Fl. G. 5s	01°42'19.440"N 110°33'07.412"E	01°42'19.440"N 110°33'07.412"E
Buoy No. 6	Fl. R. 5s	01°42'19.013"N 110°33'17.356"E	01°42'19.013"N 110°33'17.356"E
Buoy No. 7	Fl. G. 5s	01°39'01.815"N 110°30'23.555"E	01°41'05.051"N 110°32'24.814"E
Buoy No. 8	Fl. R. 5s	01°38'40.000"N 110°30'30.000"E	01°40'59.456"N 110°32'32.570"E

2. Mariners are advised to update their affected charts accordingly.

Charts : SAR 11, SAR 12, SAR 13 & SAR 101

Source : Sarawak Region Marine Department, Marine Department Malaysia

Date : 29th April 2022

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600